

L Number	Hits	Search Text	DB	Time stamp
12	71	preheating with carburizing	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 14:57
13	12	preheating with carburizing with steel	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:08
14	2	preheating with carburizing with steel with continuous	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:11
15	2	preheating with carburizing with steel and continuous adj furnace	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:11
16	9	preheating with carburizing and continuous adj furnace	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:14
17	4	preheating same carburizing same steel and continuous adj furnace	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:17
18	2	4622006.pn.	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:18
19	0	preheat\$3 with because same carbur\$3	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:19
20	24	preheat\$3 with carbur\$3	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:54
23	0	preheat\$3 with austenitize same carburiz\$3	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:55
24	3	preheat\$3 with austenitize	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:55
25	114	preheat\$3 with austenit\$3	USPAT; US- PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/27 15:56
26	7	preheat\$3 with austenit\$3 same carburiz\$3	DERWENT; IBM_TDB	2004/01/27 15:56